

Central Solutions (GB) Ltd

SOL-X SERVICE LUBE WITH PTFE

K145

1. IDENTIFICATION OF THE PREPARATION AND COMPANY

PRODUCT CODE: K145
PRODUCT NAME: SOL-X SERVICE LUBE WITH PTFE
SUPPLIER: Central Solutions (GB) Ltd
Unit 59 Askern Industrial Estate
Moss Road
Askern
Doncaster
DN6 0DD

TELEPHONE: 07775 514 020

FAX: /Tel: 01405 861 667

2. COMPOSITION/INFORMATION ON INGREDIENTS

| NAME CAS No.: | EINECS Nr.: | CLASSIFICATION | CONTENT |
|------------------------------|-------------|----------------|---------|
| BUTANE 106-97-8 | 203-448-7 | F+;R12 | 10-30 % |
| DIMETHOXYMETHANE 109-87-5 | 203-714-2 | F;R11. | 5-10 % |

The full text for all R-Phrases are displayed in Section 16

3. HAZARDS IDENTIFICATION

R12 Extremely flammable.

PRESSURISED CONTAINER - increase in temperature to greater than 50C will cause internal pressure to rise

4. FIRST AID MEASURES

INHALATION: Move the exposed person to fresh air at once. Keep the affected person warm and at rest. Get prompt medical attention. For breathing difficulties oxygen may be necessary.

INGESTION: Rinse mouth thoroughly. Drink plenty of water. Get medical attention.

SKIN: Wash the skin immediately with soap and water. Get medical attention if any discomfort continues.

EYES: Promptly wash eyes with plenty of water while lifting the eye lids. Continue to rinse for at least 15 minutes. Get medical attention if any discomfort continues.

5. FIRE FIGHTING MEASURES

EXTINGUISHING MEDIA: Use:; Powder. Dry chemicals, sand, dolomite etc. Water spray, fog or mist.

SPECIAL FIRE FIGHTING PROCEDURES: Containers close to fire should be removed or cooled with water. Use water to keep fire exposed containers cool and disperse vapours.

UNUSUAL FIRE & EXPLOSIVE HAZARDS: Aerosol cans may explode in a fire.

6. ACCIDENTAL RELEASE MEASURES

SPILL CLEAN UP METHODS: Wear necessary protective equipment. Extinguish all ignition sources. Avoid sparks, flames, heat and smoking. Ventilate. If leakage cannot be stopped, evacuate area.

ENVIRONMENTAL PRECAUTIONS: Any spillage needs to be contained and not allowed to enter water courses

7. HANDLING AND STORAGE

USAGE PRECAUTIONS: Keep away from heat, sparks and open flame. Avoid spilling, skin and eye contact. Ventilate well, avoid breathing vapours. Use approved respirator if air contamination is above accepted level.

STORAGE PRECAUTIONS: Aerosol cans: Must not be exposed to direct sunlight or temperatures above 50°C.

Central Solutions (GB) Ltd

SOL-X SERVICE LUBE WITH PTFE

K145

8. EXPOSURE CONTROLS AND PERSONAL PROTECTION

| INGREDIENT NAME: | CAS No.: | STD | LT EXP 8 Hrs | ST EXP 15 Min |
|------------------|----------|-----|--------------|---------------|
| BUTANE | | WEL | 600 | 750 |

PROTECTIVE EQUIPMENT:



9. PHYSICAL AND CHEMICAL PROPERTIES

| | |
|---------------------------------|--|
| APPEARANCE: | Aerosol |
| PHYSICAL DATA COMMENTS: | Information given relates to total aerosol container contents. |
| FLASH POINT (°C): | - 74 N/A. |
| AUTO IGNITION TEMPERATURE (°C): | + 405 |
| FLAMMABILITY LIMIT - LOWER(%): | 1.8 |
| FLAMMABILITY LIMIT - UPPER(%): | 10.0 |

10. STABILITY AND REACTIVITY

| | |
|---------------------------------|--|
| STABILITY: | Stable under normal temperature conditions. |
| CONDITIONS TO AVOID: | Avoid heat, flames and other sources of ignition. Increase in temperature to greater than 50 degrees will cause rise in internal pressure with likelihood of bursting/explosion. |
| HAZARDOUS COMPOSITION PRODUCTS: | Fire creates:, Toxic gases/vapours/fumes of:, Carbon monoxide (CO). Carbon dioxide (CO2). |

11. TOXICOLOGY INFORMATION

| | |
|---------------|--|
| INHALATION: | High concentrations of vapours may irritate respiratory system and lead to headache, fatigue, nausea and vomiting. Gas or vapour displaces oxygen available for breathing (asphyxiant). Unconsciousness. |
| SKIN CONTACT: | No specific health warnings noted. |
| EYE CONTACT: | Irritation of eyes and mucous membranes. |

12. ECOLOGICAL INFORMATION

| | |
|--------------|--|
| ECOTOXICITY: | Not regarded as dangerous for the environment. |
|--------------|--|

13. DISPOSAL CONSIDERATIONS

| | |
|---------------------|--|
| DISPOSABLE METHODS: | Empty containers must not be burned because of explosion hazard., Dispose of waste and residues in accordance with local authority requirements. |
|---------------------|--|

14. TRANSPORT INFORMATION

| | |
|--------------------------|---------------------|
| UN No ROAD: | 1950 |
| UK ROAD TRANSPORT CLASS: | 2 |
| ADR CLASS NO.: | 2 |
| PROPER SHIPPING NAME I: | AEROSOLS, FLAMMABLE |
| UN No SEA: | 1950 |
| IMDG CLASS: | 2 |
| UN NO. AIR: | 1950 |
| ICAO CLASS: | 2.1 |

Central Solutions (GB) Ltd

SOL-X SERVICE LUBE WITH PTFE

K145

15. REGULATORY INFORMATION

LABEL FOR SUPPLY:**RISK PHRASES:**

R12 Extremely flammable.

SAFETY PHRASES:

S2 Keep out of the reach of children, S16 Keep away from sources of ignition - No smoking. S23 Do not breathe vapour/spray. S51 Use only in well-ventilated areas.

STATUTORY INSTRUMENTS:

Control of Substances Hazardous to Health. Chemicals (Hazard Information and Packaging) Regulations.

APPROVED CODE OF PRACTICE:

Classification and Labelling of Substances and Preparations Dangerous for Supply.

GUIDANCE NOTES:

Workplace Exposure Limits EH40. Introduction to Local Exhaust Ventilation HS(G)37. CHIP for everyone HSG(108).

16. OTHER INFORMATION

USER NOTES:

The following risk phrases relate to the raw materials in the product and not the product itself:-

REVISION DATE:

07/06/2006

REV. NO./REPL. SDS GENERATED:

6

R-PHRASES (Full Text):

R12 Extremely flammable.| R11 Highly flammable. |